ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M118239 Date Received: 12/27/07 Date Extracted: 01/02/08 Date Analyzed: 01/02/08 Matrix: Water Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Alaskan Copper Works PO M118239, F&BI 712285

712285-01 x10 712285-01 x10.046

ICPMS1 Instrument:

Operator: hr

Internal Standard: Germanium

Zinc

% Recovery: 87

12.8

Lower Limit: 60

Upper Limit: 125

Concentration Analyte: ug/L (ppb) Chromium 540 Nickel 632 Copper 610

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Alaskan Copper Works Client ID: Method Blank Client: PO M118239, F&BI 712285 Date Received: Project: Not Applicable Date Extracted: 01/02/08 Lab ID: I8-001 mb Date Analyzed: 01/02/08 Data File: I8-001 mb.044 Instrument: ICPMS1 Matrix: Water

Units: Operator: hr

ug/L (ppb)

Upper Lower Internal Standard: Limit: Limit: % Recovery: 125 Germanium 80 60

Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1 Copper <1 Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 01/08/08 Date Received: 12/27/07

Project: Metro Self Monitor, PO M118239, F&BI 712285

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 712285-01 x10 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	540	595	10	0-20
Nickel	ug/L (ppb)	632	666	5	0-20
Copper	ug/L (ppb)	610	640	5	0-20
Zinc	ug/L (ppb)	12.8	<10	nm	0-20

Laboratory Code: 712285-01 x10 (Matrix Spike)

		Spik	e Sampl	e Recover		ıce
Analyte	Reporting I	Units Leve	l Resul	t MS	Criteri	a
Chromium	ug/L (pp	b) 200	540	162 b	50-150	
Nickel	ug/L (pp	b) 200	632	0 b	50-150)
Copper	ug/L (pp	b) 200	610	0 b	50-150) 14.
Zinc	ug/L (pp	b) 500	12.8	87	50-150	

Laboratory Code: Laboratory Control Sample

		Spike	Percent Recovery	Acceptance
Analyte	Reporting Units	Level	LCS	Criteria
Chromium	ug/L (ppb)	20	110	70-130
Nickel	ug/L (ppb)	20	108	70-130
Copper	ug/L (ppb)	20	108	70-130
Zinc	ug/L (ppb)	50	97	70-130

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc. The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

712285			SA			NOFC	US.	TOI) Y	M	E	12	21	10	<i>†</i>			H)		
send Report To Creveus A. THompson			SAMPLERS (signature)									Page # of TURNAROUND TIME								
Company ALASKAN CORPORK Works			PROJ	ECT NA	ME/NO.)#		☐ Standard (2 Weeks)						
Address 628 S. Handow St.			medeo Grab M118239								39	Rush charges authorized by:								
			REMARKS									\dashv	SAMPLE DISPOSAL							
City, State, ZIP Seasure WA 98/34												☐ Dispose after 30 days ☐ Return samples								
Phone # 206-571-603	33 Fax # 201	6-382-4	1309															ith instru	ctions	
											ANA	LYS	ES R	EQU	EST	ED				
						21	7	ne	21B	09	270		3				1			
Sample ID	Lab ID	Date	Time	Some	le Type	# of	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	57	、				N.	otes	*
Sample 1D	Lab ID	Date	Time	Samp	ite Type	containers	PH-]	H-G	EX b	Cs l	လွ	田	3					140	Jies	
				١,			H	TF	BT	×	SV		Q	`						
m 118239	01	12/27	12:30	H	.0	1							X							
				1																
					···		1									97.				
		-	1				-													
			-	-			\vdash													
		-	 				╄		-											···
					···		<u> </u>													
<u> </u>																				
							T													
							1	\vdash	T	\vdash	1.									
Friedman & Bruya, Inc.		⁄I ∕SIGNATU	JRE		T	PRIN	ΓNA	ME	<u> </u>	<u> </u>		<u> </u>	CC)MP.	ANY	L	Т	DATE	TII	ME
3012 16th Avenue West				D Genel Thompson						Acw				•	10	12/2		Spy		
Seattle, WA 98119-2029				Whan Phan						FEBI					. 16	127 107	1:0	1		
Ph. (206) 285-8282	Relinquished b	ру: /				•								-			\top			
Fax (206) 283-5044	Received by:																\top			
FORMS\COC\COC.DOC		4	:0	43	* :							<u> </u>	4		- AC	ke sak		170m		
												Sai	mple	s re	ceiv	ea a	Data	1/c		

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 8, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 27, 2007 from the Metro Self Monitor, PO M118239, F&BI 712285 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0108R.DOC